


## Roof Production Facility - The Netherlands



Before ^



Before ^



After ^



After ^

<i>Commissioned by</i>	<i>A. de Bruijn</i>
<i>Location</i>	<i>Production plant Amgen, Breda, The Netherlands</i>
<i>Year</i>	<i>2009</i>
<i>Object Type</i>	<i>Roof</i>
<i>Surface Type</i>	<i>Metal</i>
<i>Total coated surface:</i>	<i>Unknown</i>
<i>Used product(s):</i>	<i>RO ND14 - Noxyde - Pegacryl Satin</i>
<i>Technical Advice Ref:</i>	<i>HH08.0532/ah – 2235</i>
<i>Description</i>	<i>Roof was cleaned with high pressure in combination with RO ND14. After this 2 coats Noxyde (total d.f.t. 350 µm) and 1 coat Pegacryl Satin (d.f.t. 41 µm) have been applied.</i>
<i>Account Manager</i>	<i>H. Hoven</i>