

RAI PARKEERGARAGE P2 AMSTERDAM



Location	RAI Parking garage P2 in Amsterdam
Year	2008-2009
Object Type	Walls parking garage
Surface Type	Metal
Total coated surface (sqm)	Unknown
Used product(s):	Noxyde
Technical Advice Ref:	No formal advice was given
Description	Metal derusted St3. 2 coats Noxyde (d.t.f. 350 µm)
Account Manager	H. Knevel